Oil Field Environmental Incident Summary Date/Time of Notice: 10/30/2014 10:14 Incident: 20141030101438 Responsible Party: STATOIL OIL & GAS LP Well Operator: STATOIL OIL & GAS LP Well Name: ORVILLE 4-9 #2-H Field Name: TODD Well File #: 21006 **Date Incident: 10/29/2014 Time Incident: 15:00** Facility ID Number: **WILLIAMS Twp:** 155 **Rna:** 101 Sec: 33 Qtr: County: Location Description: Submitted By: Jake Way Received By: Contact Person: Jake Way 6300 BRIDGE POINT PKY, BLDG 2 SUITE 500 AUSTIN, TX 78730 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** 1 Mile 1 Mile Distance Nearest Water Well: Type of Incident: Valve/Piping Connection Leak Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled **Units** Recovered **Units Followup Units** Oil 8 **Barrels** 8 **Barrels** barrels **Brine** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: 9/1/2016 Clean Up Concluded: 10/30/2014 Risk Evaluation:

Areal Extent:

None

Potential Environmental Impacts:

Impacted well site soil will be properly disposed of.

Action Taken or Planned:

Nuts and bolts on flange will be replaced and properly tightened.

Wastes Disposal Location: PDI

Agencies Involved:

Updates

Date: 10/31/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location within the diking according to the report. NDIC retains oversight.